

GX-7 Power Amplifier

Errata Notes

The purpose of this document is to communicate any points that are not fully discussed or to correct text within the GX-7 User Guide, Part No. 070-18129, Rev 0.

Inside Front Cover - Additional Safety Instruction

The following Safety Instruction should have been included:

“Main Plug is considered to be the disconnect device for this product and shall remain readily operable.”

Page 2-3 - Update to Rear Panel Overview

The Power Requirement on the Rear Panel Overview Graphic is incorrect. It is:

120V Operation: 10A [1200W]

Page A-2 - Update to Power Requirements in Specification Table

The Power Requirements are incorrect. They are:

120V Operation: 10A [1200W] (domestic)

230V Operation: 4A [920W] (export)

Page A-3 - Update and Change to the Declaration of Conformity

The “Application of Council Directive(s)” and the “Standard(s) to Which Conformity is Declared” should state:

Application of Council Directive(s):

2004/108/EEC and 73/23/EEC as amended by 93/68/EEC

Standard(s) to Which Conformity is Declared:

EN 55013:2001 + A1:2003

EN 55020:2002 + A1:2003 + A2:2005

EN 61000-3-2:2000 + A2:2005

EN 61000-3-3:1995 + A1:2001

EN 60065:2002

Back Cover - Lexicon’s Product Shipment Address has changed

The address on the back cover is no longer valid for product shipments. The correct address is:

900 Middlesex

Bldg. #6

Billerica MA, 01821-0017



Lexicon, Inc.
3 Oak Park
Bedford, MA 01730-1413
USA

Tel 781-280-0300
Fax 781-280-0490
www.lexicon.com

Customer Service
Tel 781-280-0300
Fax 781-280-0495 (Sales)
Fax 781-280-0499 (Service)